

## Concord Campus

### ACM SURVEY RESULTS

The following homogeneous building material types were sampled as part of this survey conducted in 1994. Results are summarized in the table below:

MTL #	MATERIAL DESCRIPTION	LOCATION	F/NF <sup>1</sup>	COND. <sup>2</sup>	% ACM	# SAMP.	QUANTITY
	Pipe Hangers	Academic Services Building	NF	Good	25 %	N/A	N/A

\* Reviewed Jan. 2009- location of hangers were re-sampled and only identified one building to contain asbestos(not throughout campus as previously reported).

<sup>1</sup> F = Friable; NF = Non-friable Friability is further defined in section 4.

<sup>2</sup> Cond. = Condition Of Materials Either good, fair or poor.

\* Bay Area Air Quality Management District – identifies this material as friable for renovation and disposal purposes.

ND = None Detected

N/A = Not Applicable

SF = Square Feet